

The PHE inspection that fully meets 3A Sanitary Standards





WESTERN

9109 SE 64th Avenue | Portland, OR 97206 503.774.7342 | 800.715.8820 FAX 503.774.2550

CENTRAL

1325 Remington Rd., Ste. T Schaumburg, IL 60173 847.301.6890 | FAX 503.774.2550

EASTERN

10129 Piper Lane | Bristow, VA 20136 703.257.1660 | 800.825.8820 FAX 703.330.7940





The clear choice in PHE inspection methods

| | Plate Check™ | Helium Test | Salt Test | Air-Bubble Test |
|---|-----------------|-----------------------|--------------|--------------------|
| Fully Meets Current 3A Standard 11-09 (8/2010) | YES | NO | NO | NO |
| Measurement Sensitivity Independent of PHE's Size (Large and small units tested equally) | YES | NO | NO | NO |
| Accurately Locates Defects on All Plates | YES | NO | NO | NO |
| Utilizes Food Grade/Non-Toxic Fluids | YES | YES (PHASE 1 ONLY) | YES | YES |
| Commonly Completed on HTST's in Less than 4 hours | YES | YES (PHASE 1 ONLY) | YES | YES |
| Completely Inspects Plate and Gasket Conditions | YES | NO | NO | NO |
| Provides Feed Back on CIP Cleaning Efficiency | YES | NO | NO | NO |
| Tests the Entire Wetted Surface of Every Plate | YES | NO | NO | NO |
| Report Documents all Aspects of PHE's Condition (Frame) | YES | NO | NO | NO |
| Verifies Presence and Location of Drain Plates in HTST's | YES | NO (PHASE 2 YES) | NO | NO |











CIP Response

Gasket Condition

Plate Corrosion/Wear

Frame Condition



| WESTERN | 9109 SE 64th Avenue Portland, OR 97206 503.774.7342 800.715.8820 FAX 503.774.2550 | |
|---------|--|--|
| CENTRAL | 1325 Remington Rd., Ste. T Schaumburg, IL 60173 847.301.6890 FAX 503.774.2550 | |
| EASTERN | 10129 Piper Lane Bristow, VA 20136 703.257.1660 800.825.8820 FAX 703.330.7940 | |



www.AGCHeatTransfer.com